


CARTA DE CHEGADA PADRÃO
 POR INSTRUMENTOS (STAR)
 STANDARD ARRIVAL CHART
 INSTRUMENT (STAR)

PORTO ALEGRE / Salgado Filho, INTL (SBPA)
RWY 11
GAVIR 1A

TA 4000'	ATIS 132.35	ACC CURITIBA 127.40 126.75 128.45 135.85 121.50	APP PALEGRE 119.00 120.10 120.55 128.90 121.50	TWR PALEGRE 118.10 121.50
----------	-------------	---	---	------------------------------




1 - D-ATIS AVBL via Data Link.
 2 - Informações complementares ao verso.
 2 - See reverse side for additional information.

DOSUL
112.30 CXS

SEM ESCALA
NOT TO SCALE

PELOTAS
113.30 PTS

FIGUEIRAS
114.70 FIG



MODIFICAÇÕES / CHANGES: EAC, REG., ALTITUDE MIN., DESCRIÇÃO TEXTUAL/TEXTUAL DESCRIPTION.

DESCRIÇÃO TEXTUAL
TEXTUAL DESCRIPTION

CHEGADA GAVIR 1A

- 1 - TRNS CALVE: Manter RDL 242 FIG até DIMEP, curvar à esquerda, RDL 209 CXS até GAVIR, curvar à direita, rumo 068 até POSBI. Então ...
 - 2 - TRNS ISOGU: Manter RDL 278 FIG até GAVIR, curvar à esquerda, rumo 068 até POSBI. Então, ...
 - 3 - TRNS OBLAD: Manter RDL 268 FIG até OGSEK, curvar à esquerda, RDL 209 CXS até GAVIR, curvar à direita, rumo 068 até POSBI. Então ...
 - 4 - TRNS OPROR: Manter RDL 252 FIG até VUGOR, curvar à esquerda, RDL 209 CXS até GAVIR, curvar à direita, rumo 068 até POSBI. Então ...
 - 5 - TRNS PTS: Manter RDL 045 PTS até GENUS, curvar à esquerda, RDL 209 CXS até GAVIR, curvar à direita, rumo 068 até POSBI. Então ...
- ... Completar procedimento autorizado pelo ATC.

GAVIR 1A ARRIVAL

- 1 - CALVE TRNS: *Maintain 242 FIG RDL until DIMEP, turn left, 209 CXS RDL until GAVIR, turn right, course 068 until POSBI. Then, ...*
 - 2 - ISOGU TRNS: *Maintain 278 FIG RDL until GAVIR, turn left, course 068 until POSBI. Then, ...*
 - 3 - OBLAD TRNS: *Maintain 268 FIG RDL until OGSEK, turn left, 209 CXS RDL until GAVIR, turn right, course 068 until POSBI. Then, ...*
 - 4 - OPROR TRNS: *Maintain 252 FIG RDL until VUGOR, turn left, 209 CXS RDL until GAVIR, turn right, course 068 until POSBI. Then, ...*
 - 5 - PTS TRNS: *Maintain 045 PTS RDL until GENUS, turn left, 209 CXS RDL until GAVIR, turn right, course 068 until POSBI. Then ...*
- ... Complete procedure authorized by ATC.

FALHA DE COMUNICAÇÃO
COMMUNICATION FAILURE

Complete chegada até POSBI e execute procedimento autorizado pelo ATC.
Complete arrival until POSBI and execute procedure authorized by ATC.